

Oil Field Environmental Incident Summary

Incident: 20160824131009

Date/Time of Notice: 08/24/2016 13:10

Responsible Party: LIBERTY RESOURCES MANAGEMENT COMPANY, LLC

Well Operator: LIBERTY RESOURCES MANAGEMENT COMPANY, LLC

Well Name: ERLING 14-7H-0607-15895-MB

Field Name: TEMPLE

Well File #: 26623

Date Incident: 8/23/2016

Time Incident: 16:30

Facility ID Number:

County: WILLIAMS

Twp: 158

Rng: 95

Sec: 7

Qtr: SW SW

Location Description: Elroy Wellsite near flare.

Submitted By: Tappan Souther

Received By:

Contact Person: Tappan Souther
1200 17TH STREET, SUITE 2200
DENVER, CO 80202

General Land Use: Well/Facility Site

Affected Medium: Topsoil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Fire

Release Contained in Dike: No

Reported to NRC: No

Spilled Units

Recovered Units

Followup Units

Oil

Brine

Other

Description of Other Released Contaminant:

Flame from wellsite flare.

Inspected:

Written Report Received: 12/1/2016

Clean Up Concluded: 8/23/2016

Risk Evaluation:

None.

Areal Extent:

The burn area was estimated to be 9.5 acres.

Potential Environmental Impacts:

None.

Action Taken or Planned:

Liberty Resources will review the flare configuration, possible equipment modifications and start up procedures to determine the best path forward to prevent a similar event from happening in the future.

Wastes Disposal Location: No wastes were present.

Agencies Involved: Local Fire Department

Updates

Date: 8/24/2016 **Status:** Reviewed - Follow-up Required

Author: Schiermeister, Robin

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

According to the report, the fire went off site. More follow-up is needed.

Date: 9/28/2016 **Status:** Inspection

Author: O'Gorman, Brian

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Arrived on location at 11:30. 59 degrees F, sunny, west wind 0-5 mph. Walked the area and took photos. It appeared that no product had impacted areas off site; there was only burnt vegetation as the report described. No further follow-up needed at this time.